

TRENCH REPAIR

NOTES:

- 1. BACKFILL PLACED BELOW AGGREGATE BASE ROCK OR PAVEMENT SHALL BE COMPACTED TO 95% RELATIVE COMPACTION.
- 2. TACK COAT SHALL BE LIQUID ASPHALT SS-1 CONFORMING TO SECTION 94 OF THE STANDARD SPECIFICATIONS.
- 3. FOR REPAIR TO FINISH SURFACES NOT SHOWN, SEE PROJECT PLANS AND SPECIFICATIONS.

(4)	TRENCH REPAIR						STD PLAN
	DRAWN	CR	KEY	REVISIONS	DATE	APPROVED (1)	702
	CHECKED	GG	<u></u>	CRIGINAL ISSUE	06-21-17	Hum D Gilet 1.	
						GLENN GILCHEIST, PE, DESIGN MANAGER, ASD DIV.	SHEET 1 OF 1
	OPERATIONS					DATE 6/21/2017	NOT TO SCALE
EAST BAY REGIONAL PARK DISTRICT - STANDARD PLANS							