



### Trail Uses



Hiking



Bicycling



Equestrian



Dogs



No Motorized Vehicles

### Hazards and Obstructions



Ruts  
2 in.

# Nimitz Way

Tilden Regional Park

## Trail Length 4.1 mi (6.6 km)

### Network trail

Nimitz trail is a good place to see hawks, raptors, migratory golden eagles enjoyed by bird watchers. Nimitz attracts a broad range of trail users, including runners, families, and cyclists. Opens up to great views of San Pablo reservoir, SF bay and Mt Diablo. Nimitz Way is also a segment of the National Skyline Trail.

Cumulative Gain 343 ft (105 m)  
Elevation Change Loss 300 ft (91 m)



### Typical Grade is 3.0%

5% of the trail is between 8% and 13%  
100 ft (30 m) is between 12% and 13%  
8% grade is a standard ramp.



### Typical Cross Slope is 3.4%

7% of the trail is between 8% and 30%  
416 ft (127 m) is between 12% and 30%



### Typical Tread Width is 114 in (291 cm)

Tread Width ranges from 95 in (241 cm) to 204 in (518 cm)  
Minimum Clearance 39 in (99 cm)



### Trail Surface is Asphalt

100% of the trail is Paved  
0 ft (0 m) of the trail is Soft or worse

### Trailhead Location

Trail begins at Inspiration Point off of Wildcat Canyon Rd.



### Trail Access Information

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

Obstructions less than 0.5 in (2.5 cm) or outside the tread area width by highway are not measured. Minimum clearance boundaries were at least 0.5 in (2.5 cm) high.

This report has been generated by TrailWare which has been created by Beneficial Designs, Inc.

# Nimitz Way

---

Length 4.1 mi (6.6 km)

Network trail

---



Hiking



Bicycling



Equestrian

---



Typical Grade 3.0%

---

5% of the trail is

8% to 13%

---

100 ft (30 m) is 12% to 13%  
8% grade is a standard ramp.

---



Typical Cross Slope 3.4%

---

7% of the trail is

8% to 30%

---

416 ft (127 m) is 12% to 30%

---



Typical Tread Width

114 in (291 cm)

---

Minimum 95 in (241 cm)

Maximum 204 in (518 cm)

Minimum Clearance 39 in (99 cm)

---



Asphalt

---

100% is Paved

---

0 ft (0 m) is Softer or worse

---



Ruts 2 in.

---



Trail Access  
Information



Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

This report is generated by TrailWare which has been created by Beneficial Designs Inc.

Aug 25, 05

**Nimitz Way**  
**Tilden Regional Park**  
**Trail Access Information Summary**  
**Trail Length 4.1 mi (6.6 km)**  
**Network trail**

First Segment Assessed  
Last Segment Assessed

page 1  
Jun 13, 05  
Jun 14, 05

**Cumulative Elevation Change**

Gain 343 ft (105 m)  
Loss 300 ft (91 m)

---

**Typical Grade is 3.0%**

5% of the trail is between 8% and 13%  
100 ft (30 m) is between 12% and 13%  
8% grade is a standard ramp.  
Locations and lengths can be found on the Maximum Grade Table Reports

---

**Typical Cross Slope is 3.4%**

7% of the trail is between 8% and 30%  
416 ft (127 m) is between 12% and 30%  
Locations and lengths can be found on the Maximum X-Slope Table Reports

---

**Typical Tread Width is 114 in (291 cm)**

Tread Width ranges from 95 in (241 cm) to 204 in (518 cm)  
**Minimum Clearance Width is 39 in (99 cm)**  
Locations and lengths can be found on the Minimum Tread Width Table and Minimum Clearance Width Reports

---

**Trail Surface is Asphalt**

100% of the trail is Paved  
0 ft (0 m) of the trail is Soft or worse  
Length of trail can be found on the Surface Type Table and Surface Category Table Reports.

---

**Obstructions**

Ruts 2 in.

Locations and lengths can be found on the Minimum Vertical and Maximum Tread Obstructions Reports

---

**Trail Uses**

Hiking  
Bicycling  
Equestrian

---

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or land slides) may not have been mapped. Maximum grades and cross slopes may vary. Obstructions less than 0.5 in (2.5 cm) or outside of the tread area are wide by high were not measured. Minimum clearance boundaries were at least 0.5 in (2.5 cm) high.