

Trail Uses



Hiking



Bicveline



Dogs



No Motorized Vehicles

Hazards and Obstructions



Ruts

Bay View Trail

Coyote Hills

Trail Length 3.1 mi (5 km)

Linear trail

Bay ViewTrail is a be autiful hike along the San Francisco Bay. Along the way you will run across a wide variety of birds such as Pelicans, Egrets, and Marsh hawks.

Cumulative Gain 156ft (48 m) Elevation Change Loss 179 ft (54 m)



Typical Grade is 2.1%

2% of the trail is between 8% and 12% 170 ft (52 m) is between 12% and 12% 8% grade is a standard ramp.



Typical Cross Slope is 3.1%

20% of the trail is between 5% and 11% 112 ft (34 m) is between 10% and 11%



Typical Tread Width is 106 in (269 cm)

Tread Width ranges from 80 in (203 cm) to 208 in (528 cm) Minimum Clearance 32 in (81 cm)



Trail Surface is Asphalt

100% of the trail is Paved
0 ft (0 m) of the trail is Soft or worse

Trailhead Location

This trail begins at the end of Patterson Ranch road.



Warning Trailconditions may have changed since this trail was assessed Temporary obstructions (e.g. fallent rees or land slides) may not have been mapped Maximum grades and cross slopes may vary.

Obstructions bess than 0.5 in (2.5 cm) or outside the treadarea wide by 120 in (3m) high were not measured. Mhimumdear anceboundaries wiere at beast 0.5 in (25 cm) high.

This report has been generated by TiailWarew hich has been created by Beneficial Designs, Inc.

Bay View Trail

Length 3.1 mi (5 km)

Linear trail



Hiking



Bicycling



Dogs



Typical Grade 2.1%

2% of the trail is 8% to 12%

170 ft (52 m) is 12% to 12% 8% grade is a standard ramp.



Typical Cross Slope 3.1%

20% of the trail is 5% to 11%

112 ft (34 m) is 10% to 11%



Typical Tread Width 106 in (269 cm)

Minimum 80 in (203 cm)

Maximum 208 in (528 cm)

Minimum Clearance 32 in (81 cm)



Asphalt

100% is Paved

0 ft (0 m) is Softor worse



Ruts

3 in.



Trail Access Information



Warring: Trail conditions may have changed since thistrail wasassessed. Temporary dostructions(e.g. fallen trees or land slides) may not have been mapped. Maximum grades and crossslopes may vary.

This report is generated by TrailWare which has been created by Beneficial Designs Inc.

Aug 26, 05

Bay View Trail

Coyote Hills

Trail Access Information Summary

Trail Length 3.1 mi (5 km)

Lin ear trail

Cumulative Bevation Change

Gain 156ft (48 m) Loss 179ft (54 m)

Typical Grade is 2.1%

2% of the trail is between 8% and 12% 170 ft (52 m) is between 12% and 12% 8% grade is a standard ramp.
Locations and lengths can be found on the Maximum Grade Table Reports

Typical Cross Slope is 3.1%

20% of the trail is between 5% and 11% 112 ft (34 m) is between 10% and 11% Locations and lengths can be found on the Maximum X-Sbpe Table Reports

Typical Tread Width is 106 in (269 cm)

Tread Width ranges from 80 in (203 cm) to 208 in (528 cm)

Minimum Clearance Width is 32 in (81 cm)

 $Locations\ and lengths\ can be\ found on\ the\ Minimum\ Tread\ Width\ Table\ and\ Minimum\ Clear\ anc\ e\ Width\ Reports$

Trail Surface is Asphalt

100% of the trail is Paved

0 ft (0 m) of the trail is Soft or worse

 $Length of\ trail can be found\ on the Surface Type\ Table\ and\ Surface\ Category\ Table\ Reports.$

Obstructions

Ruts 3in.

Locations and lengths can be found on the Minimum Vertical and Maximum Tread Obstructions Reports

Trail Uses

Hikin g

Bicycling

Dogs

Warring Trailconditions may have changed since this trail was assessed Temporary do structions (e.g. fallent rees or land sides) may not have been mapped. Maximum grades and cross slopes may vary. Obstructions besithan 0.5 in (2.5 cm) or outside of the tread area wide by 120 in (3 m) high war enot measured. Minimum dear ance boundaries were at best 0.5 in (2.5 cm) high.

page1

Jul 26,05

Jul 27, 05

First Segment As sessed

Last Segment Assessed