



### Trail Uses



Bicycling



Dogs



Equestrian



Hiking



No Motorized Vehicles

## Bayview Trail

Point Pinole Regional Park

### Trail Length 1.7 mi (2.7 km)

#### Network trail

If a paved trail doesn't suit your needs, then this trail should do the trick. With comfortably rocke d paths, and friendly visits from the local wild life, the Bayview Trail will take you right along the Bay giving you clean air, and a cool breeze.

Cumulative Gain 110ft (33 m)  
Elevation Change Loss 147 ft (45 m)



#### Typical Grade is 2.9%

14% of the trail is between 8% and 16%  
302 ft (92 m) is between 12% and 16%  
8% grade is a standard ramp.



#### Typical Cross Slope is 4.3%

12% of the trail is between 8% and 60%  
311 ft (95 m) is between 12% and 60%



#### Typical Tread Width is 100 in (255 cm)

Tread Width ranges from 80 in (203 cm) to 155 in (394 cm)



#### Trail Surface is Aggregate/Gravel

79% of the trail is Firm or better  
1850 ft (564 m) of the trail is Soft or worse

#### Trailhead Location

This trail begins along the Point Pinole Trail right after the rail road



### Trail Access Information

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

Obstructions less than 2.0 in (5.0 cm) or outside the tread area 120 in (3 m) wide by 120 in (3 m) high were not measured. Minimum clearance boundaries were at least 20 in (50 cm) high.

This report has been generated by TrailWare which has been created by Beneficial Designs, Inc.

# Bayview Trail

---

Length 1.7 mi (2.7 km)

Network trail

---



Bicycling



Dogs



Equestrian

---



Typical Grade 2.9%

---

14% of the trail is  
8% to 16%

---

302 ft (92 m) is 12% to 16%  
8% grade is a standard ramp.

---



Typical Cross Slope 4.3%

---

12% of the trail is  
8% to 60%

---

311 ft (95 m) is 12% to 60%

---



Typical Tread Width  
100 in (255 cm)

---

Minimum 80 in (203 cm)

Maximum 155 in (394 cm)

---



Aggregate/Gravel

---

79% is Firm or better

---

1850 ft (564 m) is Soft or worse

---



Trail Access  
Information



Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

This report is generated by TrailWare which has been created by Beneficial Designs Inc.

Aug 26, 05

**Bayview Trail**  
**Point Pinole Regional Park**  
**Trail Access Information Summary**  
**Trail Length 1.7 mi (2.7 km)**  
**Network trail**

First Segment Assessed  
Last Segment Assessed

page 1  
Aug 5, 05  
Aug 5, 05

**Cumulative Elevation Change**

Gain 110 ft (33 m)

Loss 147 ft (45 m)

---

**Typical Grade is 2.9%**

14% of the trail is between 8% and 16%

302 ft (92 m) is between 12% and 16%

8% grade is a standard ramp.

Locations and lengths can be found on the Maximum Grade Table Reports

---

**Typical Cross Slope is 4.3%**

12% of the trail is between 8% and 60%

311 ft (95 m) is between 12% and 60%

Locations and lengths can be found on the Maximum X-Slope Table Reports

---

**Typical Tread Width is 100 in (255 cm)**

Tread Width ranges from 80 in (203 cm) to 155 in (394 cm)

Locations and lengths can be found on the Minimum Tread Width Table and Minimum Clearance Width Reports

---

**Trail Surface is Aggregate/Gravel**

79% of the trail is Firm or better

1850 ft (564 m) of the trail is Soft or worse

Length of trail can be found on the Surface Type Table and Surface Category Table Reports.

---

**Obstructions**

Locations and lengths can be found on the Minimum Vertical and Maximum Tread Obstructions Reports

---

**Trail Uses**

Bicycling

Dogs

Equestrian

---

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary. Obstructions less than 2.0 in (5.0 cm) or outside of the tread area a 120 in (3 m) wide by 120 in (3 m) high were not measured. Minimum clearance boundaries were at least 2.0 in (5.0 cm) high.